

Tow-Boot 2021.10 (Oct 04 2021 - 15:09:26 +0000)004 [variant: spi]

SoC: Rockchip rk3399

Reset cause: POR

Model: Pine64 Pinebook Pro

DRAM: 3.9 GiB

PMIC: RK808

MMC: mmc@fe310000: 3, mmc@fe320000: 1, mmc@fe330000: 0

Loading Environment from SPIFlash... SF: Detected gd25q128 with page size 256 Bytes, erase size 4 KiB, total 16 MiB

Warning - bad CRC, using default environment

In: serial

Out: vidconsole

Err: vidconsole

Model: Pine64 Pinebook Pro

Net: No ethernet found.

starting USB...

Bus usb@fe380000: USB EHCI 1.00

Bus usb@fe3a0000: USB OHCI 1.0

Bus usb@fe3c0000: USB EHCI 1.00

Bus usb@fe3e0000: USB OHCI 1.0

Bus usb@fe800000: usb maximum-speed not found

Register 2000140 NbrPorts 2

Starting the controller

USB XHCI 1.10

Bus usb@fe900000: usb maximum-speed not found

Register 2000140 NbrPorts 2

Starting the controller

USB XHCI 1.10

scanning bus usb@fe380000 for devices... 1 USB Device(s) found

scanning bus usb@fe3a0000 for devices... 2 USB Device(s) found

scanning bus usb@fe3c0000 for devices... 3 USB Device(s) found

scanning bus usb@fe3e0000 for devices... 1 USB Device(s) found

scanning bus usb@fe800000 for devices... 1 USB Device(s) found

scanning bus usb@fe900000 for devices... 1 USB Device(s) found

scanning usb for storage devices... 0 Storage Device(s) found

Tow-Boot